

Taiwan SSHAC Level 3 Project Kick-off Meeting Agenda

August 18, 2015 (Tue.)
NCREE R101, Taipei, Taiwan

Session	Time	Topic	Duration (min.)	Speaker
Day 1		09:00 ~ 12:00		
Project Introduction	09:00 ~ 09:10	Opening Remarks	10	PM TPC
	09:10 ~ 09:30	Project Introduction (Content, Organization, Schedule, Kick-off Meeting Agenda)	20	PM
09:30 ~ 10:00		Discussion		
Site Hazard Report	10:00 ~ 10:40	Hazard Report of NPP Sites - Part I	40	PTI
10:40 ~ 11:00		<i>Break</i>		
Site Hazard Report	11:00 ~ 11:40	Hazard Report of NPP Sites - Part II	40	PTI
11:40 ~ 12:00		Discussion		
12:00 ~ 13:30		<i>Lunch</i>		
Day 1		13:30 ~ 17:10		
GMC Issues	13:30 ~ 14:20	GMC Hazard Sensitivity	50	PTI
	14:20 ~ 15:20	Strong Ground Motion Database	60	GMC TI
15:20 ~ 15:40		<i>Break</i>		
GMC Issues	15:40 ~ 16:20	Site Parameters of NPP Sites	40	GMC TI
	16:20 ~ 17:00	GMC Tasks and Issues	40	GMC TI
17:00 ~ 17:10		Summary on Project Plan Content		
17:10 ~ 17:20		<i>Break</i>		
17:20 ~ 18:00		Summary of Today's Meeting (PM, PPRP, PTI and TI Lead) at R203 and R209		

Taiwan SSHAC Level 3 Project Kick-off Meeting Agenda

August 19, 2015 (Wed.)
NCREE R101, Taipei, Taiwan

Session	Time	Topic	Duration (min.)	Speaker
Day 2		09:00 ~ 12:00		
SSC Issues	09:00 ~ 10:00	Fault Geometry of NPP Sites and Vicinity	60	SSC TI
10:00 ~ 10:20		Discussion		
10:20 ~ 10:40		<i>Break</i>		
SSC Issues	10:40 ~ 11:40	SSC Hazard Sensitivity	60	PTI
11:40 ~ 12:00		Discussion		
12:00 ~ 13:30		<i>Lunch</i>		
Day 2		13:30 ~ 17:10		
SSC Issues	13:30 ~ 15:30	Development of Database: Previous and Recent Acquired Data	120	SSC TI
15:30 ~ 15:50		<i>Break</i>		
SSC Issues	15:50 ~ 16:20	SSC Tasks and Issues	30	SSC TI
16:20 ~ 17:10		Summary on Project Plan Content		
17:10 ~ 17:20		<i>Break</i>		
17:20 ~ 18:00		Summary of Today's Meeting and Recommendations (PM, PPRP, PTI and TI Lead) at R203 and R209		